

**CORRECTION:** An error appeared in the drawing showing the hole location for the threaded insert in the Horizontal Tilt-top Router Table project found in the December 2009 issue of *Woodworker's Journal*. The drawing below shows the corrected measurement in red. We apologize for the error.

