



**Plywood Cutting Diagram**  
(Top View)




**MATERIAL LIST**

	T x W x L
1 Top Step (1)	3/4" x 12" x 10 <sup>5</sup> / <sub>8</sub> "
2 Risers (4)	3/4" x 12" x 5 <sup>1</sup> / <sub>2</sub> "
3 Second Step (1)	3/4" x 12" x 21 <sup>1</sup> / <sub>4</sub> "
4 Bottom Step (1)	3/4" x 12" x 26 <sup>7</sup> / <sub>16</sub> "
5 Left Vertical Support (1)	3/4" x 12" x 11"
6 Left End Support (1)	3/4" x 5 <sup>3</sup> / <sub>16</sub> " x 11"*
7 Right End Support (1)	3/4" x 4 <sup>3</sup> / <sub>4</sub> " x 5 <sup>1</sup> / <sub>4</sub> "*


\* Dry-fit, mark and cut to fit




**Second Step**  
(Top View)



**Bottom Step**  
(Top View)




**Bottom Left Riser**  
(Side View)



**NOTE:** All the dados and grooves are the width of the bit and 1/4" deep.

**Left Vertical Support**  
(Side View)



**Top Step**  
(Bottom View)

